<b>INSPECTION REPORT</b>
--------------------------

QUALITY VALUED. CONFIDENCE DELIVERED

Service	Pre-shipment Inspection		
Report No. V-2404538			
Date Issued	2024-04-18	P1/23	

### **INSPECTION REPORT**

<b>1. INSPECTION IN</b>	NFORMATION		
Client:	eWheels LLC		
Supplier:	Begode		
Factory:	Begode		
Product:	Unicycles		
P.O. No.:	NA		
P.O. Quantity:	50 pcs		
Item No.:	Extreme Bull		
Inspection Date:	2024-04-17		A CONTRACTOR OF A CONTRACTOR
Location:	Dongguan City, Guangdor	ng Province, China	
Inspector:	Rocky Liu		

2. INSPECTION RESULT				
Category	Conform	Not Conform	Pending	Remark
Workmanship/Function	$\checkmark$			
Special Check Points	$\checkmark$			

OVERALL CONCLUSION	CONFORM
	Approved by: Carol Pan

QUALITY VALUED. CONFIDENCE DELIVERED


Service	Pre-shipment Inspection		
Report No.	oort No. V-2404538		
Date Issued	2024-04-18	P 2 / 23	

#### 3. REMARK POINT

- | -

#### Check Points (Patton)

**Battery voltage to full** with tolerance: +/-0.5V Result:



QUALITY VALUED. CONFIDENCE DELIVERED

Service	Pre-shipment Inspection		
Report No.	V-2404538		
Date Issued 2024-04-18 P 3 / 2		P3/23	

Actual Checked Battery Voltage against Voltage by App	
Actual Checked: 131.1 131 131.1 130.9	
By App: 130 129.9 131.3 131.9	

Battery Voltage check by App									
130	129.9	131.3	131.9	132.8	133.6	132.6	132.0	133.2	133.5
132.3	133.0								



Screenshot from the BMS information to ensure the cells are balanced & there's no error messages, cell voltages are within range. Result: OK

INSPECTION REPORT	Service	Pre-shipment Inspection	
	Report No.	V-2404538	
QUALITY VALUED. CONFIDENCE DELIVERED	Date Issued	2024-04-18	P4/23



That tires are mounted centered on the rim, with lubricating compound applied, & that there is no rubbing against fender/shell.

Result: OK



INSPECTION REPORT	Service	Pre-shipment Inspection	
	Report No.	V-2404538	
QUALITY VALUED. CONFIDENCE DELIVERED	Date Issued	2024-04-18	P 5 / 23

5 Motor rotation to check for bearing/motor issue. Result: OK, Refer to attached video





### **INSPECTION REPORT** *QUALITY VALUED. CONFIDENCE DELIVERED*

Service	Pre-shipment Inspection		
Report No.	ort No. V-2404538		
Date Issued	2024-04-18	P6/23	



0	Bearing abnormity:
0	Result: OK, Refer to attached video

4. C	DATA MEASUREMENT			
-	Function Check	(	50	Samples) : Conform
-	Special Check Points	(	50	Samples) : Conform
	NDIVIDUAL RESULT: Conform	t Conforr	n 🗌 F	Pending Refer to remark point

INSPECTION REPORT     R       QUALITY VALUED. CONFIDENCE DELIVERED     R	Service	Pre-shipment Ins	spection
	Report No.	V-2404538	
QUALITY VALUED. CONFIDENCE DELIVERED	Date Issued	2024-04-18	P7/23

#### PHOTO ATTACHMENT

01 Factory view			
1	2		
3			
02 Ro	ad tire		
01	02		

# Service Pre-shipment Inspection Report No. V-2404538 Date Issued 2024-04-18 P 8 / 23



QUALITY VALUED. CONFIDENCE DELIVERED

Service	Pre-shipment Inspection	
Report No.	V-2404538	
Date Issued	2024-04-18	P9/23




INSPECTION REPORT	Service	Pre-shipment Ins	spection
	Report No.	V-2404538	
QUALITY VALUED. CONFIDENCE DELIVERED	Date Issued	2024-04-18	P 10 / 23



### **INSPECTION REPORT** *QUALITY VALUED. CONFIDENCE DELIVERED*

Service	Pre-shipment Ins	spection
Report No.	V-2404538	
Date Issued	2024-04-18	P 11 / 23




# Service Pre-shipment Inspection Report No. V-2404538 Date Issued 2024-04-18 P 12 / 23




QUALITY VALUED. CONFIDENCE DELIVERED


Service	Pre-shipment Inspection	
Report No.	V-2404538	
Date Issued	2024-04-18	P 13 / 23




	Service	Pre-shipment Inspectio	
Report No. V-2404538		V-2404538	
	Date Issued	2024-04-18	P 14 / 23



Service	Pre-shipment Inspection	
Report No.	V-2404538	
Date Issued	2024-04-18	P 15 / 23



Service	Pre-shipment Inspection	
Report No.	. V-2404538	
Date Issued	2024-04-18	P 16 / 23




### **INSPECTION REPORT** *QUALITY VALUED. CONFIDENCE DELIVERED*


	Service	Pre-shipment Inspection	
Report No. V-240		V-2404538	
	Date Issued	2024-04-18	P 17 / 23




	Service	Pre-shipment Inspection	
	Report No.	V-2404538	
	Date Issued	2024-04-18	P 18 / 23




# Service Pre-shipment Inspection QUALITY VALUED. CONFIDENCE DELIVERED Report No. V-2404538 Date Issued 2024-04-18 P 19 / 23




# Service Pre-shipment Inspection QUALITY VALUED. CONFIDENCE DELIVERED Report No. V-2404538 Date Issued 2024-04-18 P 20 / 23



# Service Pre-shipment Inspection QUALITY VALUED. CONFIDENCE DELIVERED Report No. V-2404538 Date Issued 2024-04-18 P 21 / 23



# Service Pre-shipment Inspection QUALITY VALUED. CONFIDENCE DELIVERED Report No. V-2404538 Date Issued 2024-04-18 P 22 / 23



# Service Pre-shipment Inspection QUALITY VALUED. CONFIDENCE DELIVERED Report No. V-2404538 Date Issued 2024-04-18 P 23 / 23

