


INSPECTION REPORT

QUALITY VALUED. CONFIDENCE DELIVERED

Service	Pre-shipment Inspection	
Report No.	V-2311873	
Date Issued	2023-11-29	P 1 / 23

INSPECTION REPORT

1. INSPECTION INFORMATION

Client:	EWHEELS LLC	
Supplier:	Begode	
Factory:	Begode	
Product:	Unicycles	
P.O. No.:	-	
P.O. Quantity:	30sets	
Item No.:	Extreme Bull	
Inspection Date:	2023/11/28	
Location:	Dongguan City, Guangdong Province	
Inspector:	Henry Xiao	

2. INSPECTION RESULT

Category	Conform	Not Conform	Pending	Remark
Workmanship/Function	√			

OVERALL CONCLUSION

CONFORM

Approved by: Sunny Cai

3. REMARK POINT

-	-
NOTE	
1	Upon arrival, only 30sets were finished and under packing.
2	No assembling instruction manual was packed into packaging.
Check Points (Patton)	
1	1) Battery voltage to full: Voltage check: check the voltage when it was fully charged Actual Checked Battery Voltage against Voltage by App(spec:134.4V) Result: all the voltage of products were out of the +/-0.5V tolerance of rated voltage 134.4V; moreover, the battery voltage cannot be seen on unit's screen, and factory claimed that was the intended design.

INSPECTION REPORT

QUALITY VALUED. CONFIDENCE DELIVERED

Service	Pre-shipment Inspection	
Report No.	V-2311873	
Date Issued	2023-11-29	P 2 / 23



Battery voltage check By App:



Battery voltage check By App:



Battery voltage check By App:



Battery voltage check



Battery voltage check



Battery voltage check

Actual Checked Battery Voltage against Voltage by App



Actual Checked:	132.2	132.7	132.6					
By App:	131.8	132.8	132.3					

This reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

INSPECTION REPORT

QUALITY VALUED. CONFIDENCE DELIVERED

Service	Pre-shipment Inspection	
Report No.	V-2311873	
Date Issued	2023-11-29	P 3 / 23

Battery Voltage check by App										
131.8	132.8	132.3	132.4	132	132.3	132.6	132	131	131.9	
131.2	131.1	131	131.2	132.2	132.5	131	131	132.2	131	
131.8	131.4	131.6	132.7	132	131.5	132.1	132.8	131.5	132.8	
Motor rotation to check for bearing/motor issue. Result: Conform										
2					NIL					
Bearing abnormality: Result: Conform										
3					NIL					
4	All lights work properly Result: Conform									

This reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

INSPECTION REPORT

QUALITY VALUED. CONFIDENCE DELIVERED

Service	Pre-shipment Inspection	
Report No.	V-2311873	
Date Issued	2023-11-29	P 4 / 23



Connectivity to the App.

Result: Conform

5



That tires are mounted centered on the rim, with lubricating compound applied, & that there is no rubbing against fender/shell.

Result: Conform

6



7

Firmware is updates applied.

Result: As per APP display and factory statement, the firmware has been updated to "GW1825006"

This reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

INSPECTION REPORT

QUALITY VALUED. CONFIDENCE DELIVERED

Service	Pre-shipment Inspection	
Report No.	V-2311873	
Date Issued	2023-11-29	P 5 / 23





NIL

Screenshot from the BMS information to ensure the cells are balanced & there's no error messages, cell voltages are within range.

Result: Conform

8



INSPECTION REPORT

QUALITY VALUED. CONFIDENCE DELIVERED

Service	Pre-shipment Inspection	
Report No.	V-2311873	
Date Issued	2023-11-29	P 6 / 23

PHOTO ATTACHMENT

0 Other



1 Factory gate




2 Factory name



3 Finished products



4 Finished products



5 Packing view



6 Packing view

1 ITEM

This reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

INSPECTION REPORT

QUALITY VALUED. CONFIDENCE DELIVERED

Service	Pre-shipment Inspection	
Report No.	V-2311873	
Date Issued	2023-11-29	P 7 / 23



1 Master carton



2 Master carton



3 Main mark



4 Main mark



5 Open view of master carton



6 Packing view

This reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

INSPECTION REPORT

QUALITY VALUED. CONFIDENCE DELIVERED

Service	Pre-shipment Inspection	
Report No.	V-2311873	
Date Issued	2023-11-29	P 9 / 23



13 Accessory view



14 Accessory view



15 Accessory view



16 Accessory view



17 Accessory view



18 Accessory view

This reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

INSPECTION REPORT

QUALITY VALUED. CONFIDENCE DELIVERED


Service	Pre-shipment Inspection	
Report No.	V-2311873	
Date Issued	2023-11-29	P 10 / 23



19 Accessory view



20 Accessory view



21 Accessory view



22 Accessory view



23 Accessory view



24 Accessory view

This reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

INSPECTION REPORT

QUALITY VALUED. CONFIDENCE DELIVERED

Service	Pre-shipment Inspection	
Report No.	V-2311873	
Date Issued	2023-11-29	P 11 / 23



25 Accessory view



26 Accessory view



27 Accessory view



28 Accessory view



29 Accessory view



30 Accessory view

This reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

INSPECTION REPORT

QUALITY VALUED. CONFIDENCE DELIVERED

Service	Pre-shipment Inspection	
Report No.	V-2311873	
Date Issued	2023-11-29	P 12 / 23



31 Accessory view



32 Accessory view



33 Accessory view



34 Accessory view



35 Accessory view



36 Accessory view

This reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

INSPECTION REPORT

QUALITY VALUED. CONFIDENCE DELIVERED

Service	Pre-shipment Inspection	
Report No.	V-2311873	
Date Issued	2023-11-29	P 13 / 23



37 Accessory view



38 Accessory view



39 Accessory view



40 Accessory view



41 Accessory view



42 Accessory view

This reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

INSPECTION REPORT

QUALITY VALUED. CONFIDENCE DELIVERED

Service	Pre-shipment Inspection	
Report No.	V-2311873	
Date Issued	2023-11-29	P 14 / 23



43 Product detail view



44 Product detail view



45 Product detail view



46 Product detail view



47 Product detail view



48 Product detail view

This reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

INSPECTION REPORT

QUALITY VALUED. CONFIDENCE DELIVERED

Service	Pre-shipment Inspection	
Report No.	V-2311873	
Date Issued	2023-11-29	P 15 / 23



49 Product detail view



50 Product detail view



51 Product detail view



52 Product detail view



53 Product detail view



54 Product detail view

This reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

INSPECTION REPORT

QUALITY VALUED. CONFIDENCE DELIVERED

Service	Pre-shipment Inspection	
Report No.	V-2311873	
Date Issued	2023-11-29	P 16 / 23



55 Product detail view



56 Product detail view



57 Product detail view



58 Product detail view



59 Product detail view



60 Product detail view

This reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

INSPECTION REPORT

QUALITY VALUED. CONFIDENCE DELIVERED

Service	Pre-shipment Inspection	
Report No.	V-2311873	
Date Issued	2023-11-29	P 17 / 23



61 Product detail view



62 Product detail view



63 Product detail view



64 Product detail view



65 Product detail view



66 Product detail view

This reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

INSPECTION REPORT

QUALITY VALUED. CONFIDENCE DELIVERED

Service	Pre-shipment Inspection	
Report No.	V-2311873	
Date Issued	2023-11-29	P 18 / 23



67 Product detail view



68 Product detail view



69 Product detail view



70 Product detail view



71 Product detail view



72 Product detail view

This reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

INSPECTION REPORT

QUALITY VALUED. CONFIDENCE DELIVERED

Service	Pre-shipment Inspection	
Report No.	V-2311873	
Date Issued	2023-11-29	P 19 / 23



73 Product detail view



74 Product detail view



75 Product detail view



76 Product detail view



77 Product detail view



78 Product detail view

This reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

INSPECTION REPORT

QUALITY VALUED. CONFIDENCE DELIVERED

Service	Pre-shipment Inspection	
Report No.	V-2311873	
Date Issued	2023-11-29	P 20 / 23



79 Product detail view



80 Product detail view



81 Product detail view



82 Product detail view



83 Product detail view



84 Product detail view

This reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

INSPECTION REPORT

QUALITY VALUED. CONFIDENCE DELIVERED


Service	Pre-shipment Inspection	
Report No.	V-2311873	
Date Issued	2023-11-29	P 21 / 23



85 Product detail view



86 Product detail view



87 Product detail view

2 TEST



1 Battery voltage check



2 Battery voltage check

This reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

INSPECTION REPORT

QUALITY VALUED. CONFIDENCE DELIVERED

Service	Pre-shipment Inspection	
Report No.	V-2311873	
Date Issued	2023-11-29	P 22 / 23



3 Battery voltage check




4 Battery voltage check




5 Battery voltage check



6 Battery voltage check



7 BMS check




8 BMS check

This reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.

INSPECTION REPORT

QUALITY VALUED. CONFIDENCE DELIVERED

Service	Pre-shipment Inspection	
Report No.	V-2311873	
Date Issued	2023-11-29	P 23 / 23



9 BMS check



10 BMS check



11 BMS check



12 Function check

***** END OF REPORT *****

This reflects our findings at the time and place in inspection. This inspection has been carried out to the best of our knowledge and ability and our responsibility is limited to the exercise of reasonable one. This report does not relieve the sellers from their contractual obligations nor prejudice buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.